


mounted to a separate insulating ring, which is mounted to vertical metal brackets, which are attached to the rear of the fan housing, thereby electrically insulating the motor from the metal mounting brackets, and the fan housing. Other than the fact that both fans are box fans, there is no similarity between the Lasko front grill air divider ring, and applicants rear motor mounting electrically insulating ring.

Accordingly, it is believed that the application is in condition for allowance, and such action is requested and urged.

Respectfully submitted,


ZACHARY T. WOBENSMITH, III

Attorney for Applicant

PTO Reg. No. 26,524

6091 Carversville/Wisner Road

P.O. Box 370

Pipersville, PA 18947-0370

Telephone (215) 766-9976

RECEIVED
NOV - 8 2000
TC 3700 MAIL ROOM

RECEIVED
AUG 23 2000
TC 3700 MAIL ROOM

FIG. 5




FIG 2




FIG. 2

Approved Figs 2 & 5

CGT 1/29/01